

Page Denied

13 August 1985

MEMORANDUM FOR: Chief, NBPO/OL
FROM : Chief, Security Staff, NBPO
SUBJECT : Weekly Report 5-10 August 1985

Monday 5 August

1. 297 construction workers on site. 43 temporary badges issued.
2. 40 trucks entered the compound. Everett Steel - 2 loads of structural steel.
3. 16 persons were on site after 1700 hours (7 steel workers).
4. 166 Escort Required badges and 25 temporary Escort Required badges were issued at the security trailer.
5. 9 new contractor personnel were processed for permanent badges and security clearances.

Tuesday 6 August

1. 330 construction workers were on sites. 39 temporary badges issued.
2. 60 trucks entered the compound. Everett Steel - 3 loads of structural steel.
3. 21 persons were on site after 1700 hours (15 steel workers).
4. 166 Escort Required badges and 31 temporary Escort Required badges were issued at the security trailer.
5. 7 new contractor personnel were processed for permanent badges and security clearances.

Wednesday 7 August

1. 325 construction workers on site. 37 temporary badges issued.
2. 54 trucks entered the compound. Everett Steel - 6 loads of structural steel.
3. 20 persons were on site after 1700 hours (13 steel workers).

Wednesday 7 August continued

4. 178 Escort Required badges and 28 temporary badges were issued.
5. 9 new contractor personnel were processed for permanent badges and security clearances.
6. At 1645 hours a female Staff Employee was seen walking in the construction site, near the Hyman trailer and water tower area. When questioned, she stated she had parked her car in the West lot but had taken the shuttle to the West A lot by mistake. She had crossed into the construction site from the West A lot, walked thru the Parking deck and up the stairs, past the barriers to go to the West parking lot. She was advised that there was no way to reach the parking lot thru the construction area and given a ride to her car in West parking.

Thursday 8 August

1. 374 construction workers on site. 13 temporary badges issued.
2. 21 trucks entered the compound. Everett Steel - 4 loads of structural steel.
3. No construction workers on site after 1700 hours due to heavy rain. CENTEX Company management staff was working in their trailer.
4. 177 Escort Required badges and 29 temporary Escort Required badges were issued at the security trailer.
5. Two new contractor employees were processed for permanent badges and security clearances.

Friday 9 August

1. 334 construction workers on site. 9 temporary badges issued.
2. 57 trucks entered the compound. Everett Steel - 3 loads of structural steel.
3. 3 construction workers on site after 1700 hours (no steel workers).
4. 170 Escort Required badges and 23 temporary Escort Required badges issued at the security trailer.
5. Two new contractor personnel were processed for security clearances and permanent badges.

Saturday 10 August

1. Security support was rendered by one Staff Security Officer and 3 construction monitors for 23 construction workers.
2. 35 Steel workers were scheduled to work. 18 steel workers were on the job.

STAT



Dist: 1 - Addressee
1 - C/OPS/PAS/OS
1 - C/HSG/PSD/OS